

Reference	SSM71844
Models	Range Rover / L405 Range Rover Sport / L494
Title	L405 & L494 Range Rover / Sport Tailgate fails to operate
Category	Body
Last modified	14-May-2014 00:00:00
Symptom	112000 Latches/Locks & Security
Content	<p>Concern</p> <p>Customers may report that the Tailgate cannot be opened (either intermittently or permanently). The vehicle may have also logged DTC B1216-23 in the BCM</p> <p>Action</p> <p>Please submit an EPQR in the event a Customer should report the above concern. Land Rover Engineering will then review the EPQR and feedback as appropriate. It is imperative that a vehicle repair is not completed before receiving feedback from Land Rover Engineering.</p> <p>.</p>