

Reference	SSM71847
Models	Range Rover Evoque / L538
Title	9 speed automatic transmission faults
Category	Driveline
Last modified	15-May-2014 00:00:00
Symptom	501000 Automatic Transmission Concerns
Content	<p><u>Issue:</u> A small volume of 14 MY Evoque (L538) are flagging the following TCM DTC codes P07D4-07 or P2704-07 or P07E7-07 during SDD DTC read (which are all related to 9HP48 automatic transmission).</p> <p><u>Cause:</u> Internal transmission diagnostics have been triggered. Further investigation is required by JLR.</p> <p><u>Action:</u> If one or all of these DTC's are flagged, then: 1. Submit an EPQR detailing exact symptom and DTC's. 2. Replace transmission.</p>