

Reference	SSM66837
Models	LR2 / L359
Title	Gearshift Interlock Button / Spring Issue
Category	Driveline
Last modified	07-Jul-2014 00:00:00
Symptom	503000 Automatic Transmission Engagement Concerns
Attachments	11selector.pdf
Content	Issue: The gearshift interlock button inoperative or spring has come adrift (See Attached) Cause: The interlock button mechanism has been modified to prevent this issue from Vin No. H372254 UK Build L910950 Pune Build Action: Please only submit further EPQR's for any vehicles that are <u>post</u> the above assured VIN's

