

Reference	SSM71923
Models	Range Rover Evoque / L538
Title	Heated Windshield cracked top corner no visible impact
Category	Body
Last modified	25-Jul-2014 00:00:00
Symptom	102000 Window/Glass
Attachments	from outside.JPG
Content	<p><u>Issue:</u> Visible crack in windscreen within the areas of the top corners. See attached photograph. No impact damage visible.</p> <p><u>Cause:</u> Engineering is investigating the issue.</p> <p><u>Action:</u> In all cases please submit an ePQR with a photograph of the windscreen date code attached.</p> <p><u>UK dealerships:</u> If windscreen is removed without further damage, please retain part for PRR.</p>

