

---

<b>Reference</b>	SSM71947
<b>Models</b>	LR4 / L319 LR2 / L359 Range Rover Sport / L320
<b>Title</b>	Steering Gear Input Shaft Seal Leakage
<b>Category</b>	Chassis
<b>Last modified</b>	15-Aug-2014 00:00:00
<b>Symptom</b>	303000 Steering/Handling
<b>Attachments</b>	Input Shaft Seal and Pinion Seal.pdf
<b>Content</b>	<p><u>Issue:</u> When investigating a customer reported steering issue it is found that there is oil/fluid present around the steering gear input shaft.</p> <p><u>Cause:</u> Oil or Grease Leak past input shaft seal through normal use <b>OR</b> seal failure.</p> <p><u>Action:</u> If an input shaft seal is suspected of leaking please refer to the attached images to understand what level of grease / oil leakage is from normal operation of the steering system.</p>