



TECH TIP: Module 2 Fuse Blows Intermittently

NUMBER: TT031

MODEL: 2012 Sorento(XM)

DATE: 01/13/2014

Symptom: MODULE 2 fuse blows intermittently

Repair: In some cases, this may result from chaffed wiring harnesses in the driver's seat. Inspect the harness near the right side of the driver's seat track assembly.

Note: Tech Tips are not a substitute for proper diagnosis.