



GROUP  
BOD

MODEL  
2014~2015MY  
Sorento (XMa)

NUMBER  
PS334

DATE  
August 2014



# TECHNICAL OPERATIONS

**SUBJECT:** WIND NOISE AFTER CROSS BAR INSTALLATION

When diagnosing a concern related to wind noise coming from the roof area and the vehicle is equipped with the OE roof rack cross bars, check the roof rack cross bars to make sure they are installed correctly, using the diagram below. If the cross bars were installed incorrectly, remove the cross bars and reinstall them as shown below or by referring to the installation instructions included with the cross bar kit.

