

sp14-38

SP14-38 FRONT BUMPER HINGE REPLACEMENT

DUE TO INVENTORY SHORTAGE ON PRODUCTION LINE, THE FRONT BUMPER HINGES 411340 & 411341 DO NOT HAVE THE RIGHT PAINT FINISH (POWDER/ ECOAT). PARTS WERE PAINTED IN-HOUSE.

ON FRONT BUMPER

REPLACE LEFT & RIGHT HINGE

411340 ET 411341 QTY 1

READJUST RADAR ACCORDING TO PROCEDURE... in MI14-34 (Maintenance information bulletin)

<https://secureus5.volvoo.com/technicalpublications/pdf/Mi14-34.pdf>

DISCARD REMOVED PARTS TO RECYCLED METAL



