

Date	Expiration	Release	Page
12.2014	12.2016	1	1(4)

Release1: ORIGINAL RELEASE

MARKER LIGHT GUARD PAINT
Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, replace the IMRON painted marker light guards with powder coated marker lights.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2014	Single vehicles 2PCG33495 <u>EC735590</u> 2PCG33498 <u>EC735602</u>
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
430696	Light Guard	12

NOTE
Material can be obtained through regular channels.

PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

Replace marker light guards by 430696 rev C or higher.

NON MONTRES, REFEREZ-VOUS AU MODELE 3D SOLIDE.

-THIS DRAWING IS A LIMITED DIMENSION PRINT CREATED FROM A 3D SOLID MODEL. FOR BASIC DIMENSION NOT SHOWN REFER TO 3D SOLID MODEL.

-SAUF INDICATION CONTRAIRE, TOUTES LES TOLÉRANCES DE PROFIL

UNLESS OTHERWISE SPECIFIED, ALL PROFILES TOLERANCE

SONT/ARE :

	3	A	B	C
---	---	---	---	---

S-1-1 -SAUF INDICATION CONTRAIRE. LA LOCALISATION DE TOUS LES ELEMENTS

CYLINDRIQUES EST : $\emptyset$ $\emptyset 3$ A B C

UNLESS OTHERWISE SPECIFIED, ALL CYLINDRICAL FEATURE LOCATION IS



DOIT RENCONTRER LA SPECIFICATION D'INGENIERIE #53

MUST MEET THE ENGINEERING SPECIFICATION #53




-RAYON OBLIGATOIRE SUR LES ARETES ET COINS. TYP.2

--OBLIGATORY RADIUS ON EDGES AND CORNERS. TYP.2

[illegible]

NE PAS MESURER SUR LE DESSIN / DO NOT SCALE



Date	Expiration	Release	Page
12.2014	12.2016	1	4(4)

Return replaced parts to Prevost with A.F.A. for full reimbursement. Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately one hour (1h).

OTHER

VBC Bulletin	N/A
Fail Code	18.09
Defect Code	09
System Condition	B
Causal Part	430696

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.