



Service Bulletin

PRELIMINARY INFORMATION

Subject: Roof Beacon Lighting Harness Location

Models: 2015 Chevrolet Silverado

2014 Chevrolet Silverado 1500

2015 GMC Sierra

2014 GMC Sierra 1500

With Roof Lamp / Beacon Wiring Provisions (RPO TRW) or Snow Plow Prep Package (RPO VYU)

Some owners may question where the blunt cut wires are located for the roof beacon light.

There are two wires located directly above the overhead roof console. Remove the complete overhead roof console and the wires are taped to the harness, as shown below.

Note: The roof beacon relay is located directly above the overhead roof console.



GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION