

# **Service Bulletin**

## PRELIMINARY INFORMATION

#### Subject: 2014 Corvette 7 Speed Manual Transmission Exchange Has Ended

#### Models: 2014 Chevrolet Corvette

Equipped with 7 speed manual transmission RPO MEP or MEL

#### This PI was superseded to end part restriction. Please discard PIP5118.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### **Condition/Concern**

Effective Friday, February 7, 2014 The 7 speed manual transmission RPO MEP or MEL P/Ns 24255978, 24255981 have been removed from restriction through the PQC.

Your cooperation with this program is greatly appreciated. The internal transmission components are fully serviceable at this time.

#### **Recommendation/Instructions**

Perform published service information diagnostics, and if diagnostics lead to internal transmission repair, the parts can be ordered through your parts department and service procedures can be found in service information.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

