



Service Bulletin

PRELIMINARY INFORMATION

Subject: Speed Advisory Message Not Displaying On DIC

Models: 2009 - 2011 Cadillac DTS
With Radio (RPO U3R) Without Cruise (RPO K59)

This PI was superseded to update model years and keywords. Please discard PIC5266.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment that the Speed Advisory message does not display on the DIC.

Recommendation/Instructions

If the customer has a Cadillac DTS built with a U3R Radio but without K59 cruise, and the Speed Advisory message does not display on the DIC, do NOT replace any parts for this concern.

ADDITIONAL SI KEYWORDS:

alert navigation menu personalization warning

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION