



Service Bulletin

PRELIMINARY INFORMATION

Subject: Poor Finish On Camshafts

Models: 2011-2015 Chevrolet Express, Silverado HD
2011-2015 GMC Savana, Sierra HD
engine RPO L96 LC8 6.0L

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

When replacing the camshaft part number 12626660.


Recommendation/Instructions

Be sure to check the date code and the finish of the camshaft.

If the cam is discolored or has chatter marks, have parts department send the cam back as MR code7 new defective.



If the date code is 13360 or 14-01-14 these would be suspect camshaft.



Try to get a different camshaft with a different date code and inspect it before installing.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION