



Service Bulletin


PRELIMINARY INFORMATION

Subject: During PDI - Inspect The Front Park Halo Ring Light Operation

Models: 2015 GMC Yukon Models

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Part of the PDI inspection is to make sure all lighting is functioning properly. While performing the PDI, please make sure to check the front park halo ring lights for proper operation, shown below. The lights should be on steady with no flickering or erratic operation.



To inspect the halo ring light operation, perform a cold engine start and turn on the headlight switch to the "park" or "headlight" position. Make sure the left and right front park halo ring lights stay on steady. If any of the halo ring lights flicker or operate erratically, perform normal diagnostics. If root cause cannot be determined, replace the affected headlight.

Warranty Information

The labor time for inspecting the halo ring light operation is included in the PDI time.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION