



Service Bulletin

PRELIMINARY INFORMATION

Subject: Intermittently Radio Display Has Flickering Or Rolling Image

Models: 2014 Chevrolet Corvette Stingray

This PI was superseded to advise dealers to contact TAC. Please discard PIC5934.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

On rare occasions, a customer or dealer may comment that the radio display is blinking, flickering, rolling, or scrolling. Typical comments are that it looks like an old TV with a rolling image and that raising or lowering the display may make the concern come and go.

Recommendation/Instructions

Please contact the GM Technical Assistance Center to review the latest repair suggestions.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION