



Service Bulletin

PRELIMINARY INFORMATION

Subject: The 6.2L (RPO L86) Engine Exchange Has Ended

Models: 2014 Chevrolet Silverado
2014 GMC Sierra
Equipped with 6.2L Engine (RPO L86)

This PI was superseded to end exchange. Please discard PIP5114D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The 6.2L (RPO L86) Engine Exchange has ended

The 6.2L (RPO L86) ENGINE can now be repaired as needed or can be ordered using P/N 12657206 through the regular CCA parts process.

Recommendation/Instructions

GM Engineering would like to thank all dealers that participated in this Engine Exchange.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION