



Service Bulletin

PRELIMINARY INFORMATION

Subject: DIC Message Press Check To Turn Off Motion Sensor

Models: 2007-2014 Cadillac Escalade Models
2007-2013 Chevrolet Avalanche, Silverado, Suburban, Tahoe
2014 Chevrolet Silverado 2500/3500, Suburban, Tahoe
2007-2013 GMC Sierra, Yukon Models
2014 GMC Sierra 2500/3500, Yukon Models

This PI was superseded to update Model Years. Please discard PIT5067.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers or dealers may comment that they have a "Press check to turn off motion sensor" message on the DIC, Then, after about 10 seconds, the DIC reads "Motion sensor on".

Recommendation/Instructions

If this message is displayed, the vehicle has a GM Accessory shock sensor, motion sensor or inclination sensor installed. This is normal operation with this accessory installed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION