



Service Bulletin

PRELIMINARY INFORMATION

Subject: 2014 Cruze Diesel Engine Exchange Program Has Ended

Models: 2014 Chevrolet Cruze
Equipped with 2.0L Diesel Engine (RPO LUZ)

This PI was superseded to update Condition/Concern. Please discard PIP5116.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

2014 Cruze Diesel Engine Exchange Program Has Ended.

Technicians should use SI for normal diagnosis and repair procedures.

Part number 55584313 can now be ordered through the regular CCA parts process.

Note: Some dealers may still be required to contact the Product Quality Center (PQC) for authorization of engine assembly replacement. Refer to the latest version of bulletin 02-07-30-029 for more details.

Recommendation/Instructions

GM Engineering would like to thank all dealers that participated in this parts restriction.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION