



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** PQC Part Restriction - E92 ECM Restriction Part Number 12662034

**Models:** 2015 Chevrolet Tahoe, Suburban with V8 (L83, L86) gas engine  
2015 Chevrolet Colorado with LFX engine  
2015 GMC Yukon and Yukon XL with V8 (L83, L86) gas engine  
2015 GMC Canyon with LFX engine  
2015 Cadillac Escalade with V8 (L86) gas engine  
2015 Chevrolet Silverado/GMC Sierra with V6 (LV1, LV3) or V8 (L83, L86) gas engine  
2015 Chevrolet Corvette with LT1 & LT4 engine  
2015 Cadillac XTS with LF3 engine  
2015 Cadillac CTS with LF3, LFX engine  
2015 Cadillac ATS with LFX engine

*This PI was superseded to update Model Years. Please discard PIP5223.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

As part of our ongoing quality improvement efforts, the E92 ECM, part number 12662034 is on restriction through the PQC to assist GM Engineering with product feedback

Restricted Part Number: 12662034

### Recommendation/Instructions

If your diagnostics using SI, have led to the replacement of the ECM, please complete the following BEFORE contacting the PQC at 1-866-654-7654.

Your Name/Position:

Your Direct Phone Number:

Q1: Is the Restricted part being requested for:

- Customer Pay
- A Model Year Not Listed
- A Vehicle Line Not Listed

Complete the following if you are working on a 2015 Chevrolet Silverado Subarn Tahoe / GMC Sierra Yukon, Cadillac Escalade equipped with LV1, LV3, L83 and L86 gas engines (not L96 or LC8 gas engines and not the Duramax diesel engine), 2015 Chevrolet Colorado with LFX engine 2015 GMC Canyon with LFX engine Chevrolet Corvette with LT1 engine, Cadillac XTS with LF3 engine, Cadillac CTS with LF3, LFX engines, Cadillac ATS with LFX.

Q2: Customer's Concern:

If SES light is on, what is the DTC?

List all history and current (active) DTCs in all control modules:

**Note:** If P0700 is present in the ECM, it should NOT be necessary to replace the ECM.

The P0700 DTC is caused by a concern from the TCM and should be accompanied by another DTC.

Please refer to the appropriate trouble tree on SI for the DTC that accompanied TCM P0700 to resolve the concern.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION