



Service Bulletin

File in Section: -

Bulletin No.: P11331

Date: October, 2014

PRELIMINARY INFORMATION

Subject: Incorrect Icon for Power Assist Step/Running Board Switch

Models: 2015 Chevrolet Suburban, Tahoe
2015 GMC Yukon Models
Equipped with RPOs BRS, JF4, UFL (EXC JHD)

Condition/Concern

During PDI Inspection it may be noticed that the multi-switch pod located left of the instrument cluster may be missing the power assist step/running board switch. The typical location for this switch may instead show hill descent control.

Some vehicles may have been built with the correct switch part number but produced with the wrong icon for the power assist step/running board button as shown below.

①



Legend

(1) Incorrect Icon

3995324

②



3995325

Legend

(2) Correct Icon

Only the VINs listed below may be affected.

VIN LIST		
1GKS27KJXFR277149	1GKS2CKJ0FR277864	1GKS2CKJ1FR277419
1GKS2CKJ2FR277624	1GKS2CKJ3FR278006	1GKS2CKJ4FR277267
1GKS2CKJ4FR277351	1GKS2CKJ4FR277432	1GKS2JKJ0FR278565
1GKS2JKJXFR277391	1GNSKCKC0FR277822	1GNSKCKC1FR277375
1GNSKCKC1FR277389	1GNSKCKC1FR277554	1GNSKCKC1FR277618
1GNSKCKC3FR277104	1GNSKCKC4FR277211	1GNSKCKC6FR277713
1GNSKCKC6FR277789	1GNSKCKC7FR277977	1GNSKCKCXFR278542
1GNSKCKC8FR277518	1GNSKCKC9FR278158	

Recommendation/Instructions

If identified as having an incorrect icon, technicians should replace the switch pod using the part number listed below. Refer to Vehicle Stability Control System Switch Replacement in SI.

Parts Information

Part Number	Description
22827588	SWITCH ASM-VEH STABILITY CONT SYS

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2410920	Electronic Traction Control and Vehicle Stability Control Switch Replacement	Use Published Labor Operation Time