



Service Bulletin

PRELIMINARY INFORMATION

Subject: Rear End / Decklid Spoiler Replacement Labor Code Information

Models: 2014 - 2015 Chevrolet Impala
With Dealer-Installed Spoiler (RPO SB2) or Plant-Installed Spoiler (RPO T43)

It has been found that the incorrect labor code could be used when replacing a Dealer-Installed GM Accessories Rear End / Decklid Spoiler.

Specific labor codes have been set up in the following location of the labor time guide relative to the repair / replacement of GM Accessories:

General Information > Dealer Installed GM Accessory Repairs

Please use the appropriate labor code reflected in the matrix below when replacing a rear end / decklid spoiler.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
0522210	Rear End Spoiler Replacement - Dealer Installed (RPO SB2)	Use Published Labor Operation Time
1011290	Rear End Spoiler Replacement - Plant Installed (RPO T43)	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION