



Service Bulletin

PRELIMINARY INFORMATION

Subject: Squeak Noise Heard When Operating Clutch Pedal

Models: 2011-2015 Chevrolet Cruze
With manual transmission M32

This PI was superseded to update Model Years. Please discard PIP5242.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a squeak noise when operating the clutch pedal. This condition may be due to incompatibility between the plastic pivot pin and the plastic clutch pedal.

Recommendation/Instructions

Please contact GM TAC if you are working on a 2010-2015 Chevrolet Cruze (with manual transmission M32) with the concern of a squeak noise when operating the clutch pedal.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION