



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: VIS / GWM / IVH May Not Match Actual Audio System of Vehicle

Models: 2015 Chevrolet Colorado
2015 GMC Canyon
With Radio RPO IO6

Condition/Concern

In some cases, it may be found that some GM computer systems (IVH / VIS / GWM, etc.) do not properly show the correct audio system of the vehicle.

Recommendation/Instructions

Please refer to the SPID label located in the glove box to verify the correct audio amplifier configuration to ensure correct schematics and diagnostics are followed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION