



Service Bulletin

PRELIMINARY INFORMATION

Subject: Adding NPP Performance Exhaust

Models: 2014 - 2015 Chevrolet Corvette Stingray

This PI was superseded to update Model Years. Please discard PIC5985.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A dealer or customer may enquire if RPO NPP (Performance Exhaust System) can be added to a Stingray that was produced without the option.

Recommendation/Instructions

Do NOT attempt to add RPO NPP (Performance Exhaust System) to a car that was not manufactured with it. General Motors does not support the software changes that are required

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION