

December 17, 2014

BTB 01176 (1412)

New Warranty Instructions for TPMS-Related Repairs

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2013–15	ILX	ALL	ALL
2013–14	ILX Hybrid	ALL	ALL
2004–15	MDX	ALL	ALL
2007–15	RDX	ALL	ALL
2005–12	RL	ALL	ALL
2014–15	RLX	ALL	ALL
2014	RLX Sport Hybrid	ALL	ALL
2006–14	TL	ALL	ALL
2015	TLX	ALL	ALL
2007–14	TSX	ALL	ALL
2010–13	ZDX	ALL	ALL

BACKGROUND INFORMATION

For any TPMS-related warranty repairs, all recorded DTCs must now be entered into the warranty claim. Make sure your repair order includes those DTCs.

WARRANTY CLAIM INFORMATION

Any TPMS-related claims submitted without a DTC entered in the DTC field will be returned with **Error Code of 2077**.

American Honda does not pay for warranty claims for the following:

- Adjusting tire pressures as a result of DTCs 11, 13, 15, 17, C1821-78, C1822-78, C1823-78, or C1824-78
- DTCs 32, 34, 36, 38, C1801-87, C1802-87, C1803-87, or C1804-87 with the TPMS indicator on due to accessory wheels being installed without following installation instructions
- A physically broken TPMS sensor caused by either the dealer or the customer
- A DTC caused by installation of incorrect sensors

For all other TPMS-related repairs, the normal warranty applies.

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.