



Countries: AUSTRALIA, BRAZIL, CANADA, UNITED STATES, PUERTO RICO, SOUTH AFRICA
Document ID: IK1600037
Availability: ISIS
Revision: 3
Major System: CAB / SLEEPER / HOOD
Created: 4/20/2007
Current Language: English
Last Modified: 3/12/2014
Other Languages: [Français](#), [Español](#),
Author: Patrick Gotschall
Viewed: 135

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 25	Not Helpful 16
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	------------------------------

Title: Seat Back Panel Wear Plate on 9000's and 5000's

Applies To: All 9000's and 5000's built prior to 12/04/06


DESCRIPTION

The seats in 5000 and 9000 models can wear against the back trim panel when reclined and/or adjusted rearward.

To correct this, you need to install the part listed below:

- 3807657C1 Plate, Wear (Med Tan)

Supporting Material:



Wear Plate

Remove three fasteners from window surround and attach wear plate with original hardware.

 Hide Details

Feedback Information

Viewed: 134
Helpful: 25
Not Helpful: 16

No Feedback Found