



**Countries:** CANADA, UNITED STATES, PUERTO RICO  
**Document ID:** IK1600062  
**Availability:** ISIS  
**Revision:** 2  
**Major System:** CAB / SLEEPER / HOOD  
**Created:** 10/16/2007  
**Current Language:** English  
**Last Modified:** 3/12/2014  
**Other Languages:** [Français](#), [Español](#),  
**Author:** Patrick Gotschall  
**Viewed:** 152

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 <a href="#">View My Bookmarks</a>				 19	 14

**Title:** ProStar Push-in Trim Fasteners Popping out or Missing

**Applies To:** ProStar

## Issue:

Push-in fasteners pop out or missing from rear trim panel.

## Repair:

Replace with longer push-in fastener, part number 3674238C1. Pre-grained parts are available and acceptable to use if parts are not available in PDC. Contact Hector for Pre-grained parts if this occurs. New fastener can be used in other locations but length may need to be modified.



 Hide Details

Feedback Information

Viewed: 151  
Helpful: 19  
Not Helpful: 14

No Feedback Found