



Countries: CANADA, UNITED STATES, PUERTO RICO
Availability: ISIS
Major System: CAB / SLEEPER / HOOD
Current Language: English
Other Languages: [Français](#), [Español](#),
Viewed: 149

Document ID: IK1600064
Revision: 2
Created: 10/16/2007
Last Modified: 3/12/2014
Author: Patrick Gotschall

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 19	 35

Title: ProStar No Idle Curtains Missing Velcro


Applies To: ProStar

Issue:

No idle curtains missing Velcro Patch (driver and passenger).

Repair:

- Missing patch will have minimal effect on the performance but patch can be sewed on if need.
- Production fix is estimated to be ready by December 1 with suffix revisions 3805702C2 (LH dark neutral) & 3805707C2 (RH- Blue).



 Hide Details

Feedback Information

Viewed: 148
Helpful: 19
Not Helpful: 35

No Feedback Found