



Countries: CANADA, UNITED STATES, PUERTO RICO

Document ID: IK1600065

Availability: ISIS

Revision: 2

Major System: CAB / SLEEPER / HOOD

Created: 10/16/2007

Current Language: English

Last Modified: 3/12/2014

Other Languages: [Français](#), [Español](#),

Author: Patrick Gotschall

Viewed: 183

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 23	 49

Title: ProStar Sleeper Buzz, Squeak, Rattle

Applies To: ProStar

Issue:

Tower cabinet door squeaks.

Repair:

Spray latch and striker with Silicone dry film lubricant.



[Hide Details](#)**Feedback Information**

Viewed: 182

Helpful: 23

Not Helpful: 49

No Feedback Found

Copyright © 2014 Navistar, Inc.