



**Countries:** CANADA, UNITED STATES, PUERTO RICO  
**Document ID:** IK1600066  
**Availability:** ISIS  
**Revision:** 2  
**Major System:** CAB / SLEEPER / HOOD  
**Created:** 10/16/2007  
**Current Language:** English  
**Last Modified:** 3/12/2014  
**Other Languages:** [Français](#), [Español](#),  
**Author:** Patrick Gotschall  
**Viewed:** 143

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 <a href="#">View My Bookmarks</a>				 26	 35

**Title:** ProStar Drawer Rattle

**Applies To:** ProStar

## Issue:

Drawer rattle.

## Repair:

- Remove current rubber bumpers located on crossover bar.
- Drill (2) 6.5 (.26in) mm holes, 20 mm (.79 in) inward from existing holes.
- Install (2) new rubber bumpers (3822105c1).
- Production fix is estimated to be ready by December 1. Contact Hector if Parts are not available.



 Hide Details

**Feedback Information**

Viewed: 142  
Helpful: 26  
Not Helpful: 35

No Feedback Found

Copyright © 2014 Navistar, Inc.