

December 4, 2014

BTB 01229 (1412)

Safety Recall: Transmission Does Not Engage Park

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2015	TLX	ALL	Check the iN VIN status for eligibility

BACKGROUND

During manufacturing of the 9-speed automatic transmission, it is possible that contamination may get into the parking pawl, or the park rod may become dislodged or broken, both of which can prevent the transmission from shifting into park. Although the shift indicator will display "Park," the park lock may not engage, allowing the vehicle to roll away and increasing the risk of a crash.

This bulletin will be revised once the repair procedure, parts information, and warranty claim information are available.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.