



Countries:	CANADA, UNITED STATES, MEXICO	Document ID:	IK1201148
Availability:		Revision:	0
Major System:	ENGINES	Created:	6/17/2014
Current Language:	English	Last Modified:	6/18/2014
Other Languages:	NONE	Author:	Keith Kierzek
Viewed:	46		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 1	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: ISX15 CM2350 X101 Rod Bearing Campaign

Applies To: Select Vehicles with ISX15 Engines

Change Log

Please refer to the change log text box below for recent changes to this article:

Date	Details
06/17/2014	Article Created

Subject

ISX15 CM2350 X101 Rod Bearing Campaign

Description

Cummins has issued a campaign to authorize the replacement of all upper and lower rod bearing shells on select ISX15 CM2350 X101 engines. The upper rod bearing shells on this Cummins authorized campaign are susceptible to material delamination.

Please refer to the "Campaigns" tab under the "Service" section on QuickServe Online to determine if this article pertains to your vehicle. The status will read **"OPEN"** for **C1517** if it pertains to your vehicle and has not yet been completed. See Figure 1 below.

The screenshot shows the Cummins QuickServe Online interface. At the top, there are navigation tabs: Manuals, Dataplate, Campaigns (highlighted), TRPs, Service Bulletins, TSBs, What's New, and Service Tools. Below these are secondary tabs: Maintenance, Fault Code Search, Symptom Search, and Related Information. The main content area displays a 'Warranty Campaigns' section with a message: 'This engine may be eligible for a field campaign or TRP. Please contact your authorized Cummins service location for details.' Below this message is a table with columns for Number, Description, and Status. The table contains one entry: C1517, ISX15 / QSX15 ROD BEARING CAMPAIGN, and OPEN.

Number	Description	Status
C1517	ISX15 / QSX15 ROD BEARING CAMPAIGN	OPEN

Figure 1: QSOL Image of Open Active Campaign C1517

Repair Procedure

For repair actions and official ESN list, refer to the campaign instructions for **C1517** located on QuickServe Online.

Warranty Information

The information in this document has no effect on Navistar's present warranty coverage or repair practices, nor does it authorize campaign actions. See **C1517** on QSOL for further warranty guidelines.

Link to QuickServe Online:

<https://quickserve.cummins.com/qs3/portal/index.html>

 Hide Details

Feedback Information

Viewed: 45
Helpful: 1
Not Helpful: 0

No Feedback Found

Copyright © 2014 Navistar, Inc.