

Tech Tip No:	TT-14-016
Group:	99-Miscellaneous
Issue Date:	6/27/2014

TECH TIP

2011MY – 2014MY Exhaust Combustion Chamber with Loose Insulation

SUBJECT VEHICLES:

2011 through 2014 model year NV8J, NJ8J, and NF8J conventional trucks.

Note: This technical tip is provided as technical information and is not authorization for a warrantable repair.

CONDITION:

During service of the exhaust aftertreatment system, the technician may visually find that the insulation within the outer shell of the combustion chamber is pushing out or loose. In the event that loose insulation is found, it is recommended to push the insulation back into the outer shell, or use a utility knife to trim off the excess insulation material. Replacement of the combustion chamber for loose or missing insulation is not recommended and is not a warrantable repair. Missing combustion chamber insulation will not cause any adverse functional effects with the exhaust aftertreatment system.

