

[Next Unread Message](#)**View Message**

**Sent on** 10 02 2014 **Expires on** 10 07 2014  
**From** Parts and Service Division  
**Subject** Request for Parts: 2007-2008 Fit MIL On with DTC 32-09 and/or 61-04 Stored

**To:** All Honda Service Managers/Advisors  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2007-2008 Fit MIL On with DTC 32-09 and/or 61-04 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2007-2008 Fits with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC 32-09 (current sensor) and/or 61-04 (open/short in the EPS motor harness) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting any further repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. DTC 32-09 and/or 61-04 must be stored.
2. Code(s) must be reset once & must come on again.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.