

[Next Unread Message](#)**View Message**

Sent on	10	02	2014	Expires on	10	07	2014
From	Parts and Service Division						
Subject	Request for Parts: 2014 MDX & RLX MIL On with DTC P0154 or P0134 Stored						

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2014 MDX & RLX MIL On with DTC P0154 or P0134 Stored

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iV message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014 MDXs & RLXs with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC P0154 (Front Air Fuel Ratio Sensor [Bank 2, Sensor 1] Heater System Malfunction) or P0134 (Rear Air Fuel Ratio Sensor [Bank 1, Sensor 1] Heater System Malfunction) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to your attempting any further repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. DTC P0154 or P0134 must be stored.
2. For 2014 MDX, both 2WD and AWD are accepted.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.