

Service Bulletin No. 3082

MODEL	D / J4500 Series	Service Information	SECTION/GROUP 8-Engine	Mar 27, 2014
SUBJECT	CUMMINS ISX ENGINE 2311 FAULT CODE			
CONDITIONS	Service Information Only			

Description:

Cummins Inc. has notified Motor Coach Industries (MCI) that customers operating a coach equipped with a Cummins ISX engine that has experienced an active 2311 fault code are instructed to contact the Cummins Service Network.

Cummins is installing a new ECM calibration that will correct the logged code.



This program is being performed only by Cummins Service Network and its authorized dealers. Therefore all parts and labor required for this program, on MCI coaches with an engine under warranty, will be provided by Cummins.