

Date	Expiration	Release	Page
03.2014	03.2016	1	1(3)

Release _ : This document supersedes previous revisions.

DRIVER'S JACKET HOOK Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, remove the existing jacket hooks and install one new hook.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2012	From 2PCG33495CC73 <u>5053</u> up to 2PCG33495CC73 <u>5232</u> incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
3201128	PLATE, MOUNTING	1
500371	SCREW, MA FL PH N500 M4-0.7x8	2
901455	J-SHAPE HOOK, 2-PRUNG	1

NOTE
Material can be obtained through regular channels.

REQUIRED TOOLS

CORDLESS DRILL & BITS	DRILL BIT Ø31/64"	PHILLIPS SCREWDRIVER
		

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

- 1) Locate the modesty panel. Behind the driver's seat, remove the existing hooks (2x) (figure 1).




FIGURE 1

- 2) Where was located the hook closer to the side window, drill a new hole horizontally located at the left of the existing one (figures 2 & 3).




FIGURE 2




FIGURE 3

- 3) Install new hook using two screws #500371 and the mounting plate #3201128 (figures 4 & 5) on the other side of modesty panel.




FIGURE 4




FIGURE 5 ON THE OTHER SIDE OF MODESTY PANEL

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 1/2 hour.

OTHER

VBC Bulletin	n/a
Fail Code	23.00
Defect Code	09
System Condition	B
Causal Part	900297

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.