



Service Bulletin 506

Strictly Confidential

January 2014

Affected ModelsTiger Sport

VIN RangeSee Appendix A

MarketsAll except Brazil, Canada and USA

SubjectOwner's Handbook

Background Information

The Pirelli Angel tyre data displayed in the Tyre Specifications section of the Owner's Handbook has changed. Therefore we have identified the need to replace the Owner's Handbook on the above models.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next service/visit to the dealership.

Identification of Affected Motorcycles

Tiger Sport models in the VIN range as listed in Appendix A.

Warranty Claim Instructions

Fault code03900192

Repair code9950601 - EN Replace the Owner's Handbook with part number T3853290.

9950602 - DE Replace the Owner's Handbook with part number T3853292.

9950603 - FR Replace the Owner's Handbook with part number T3853293.

9950604 - ES Replace the Owner's Handbook with part number T3853294.

9950605 - IT Replace the Owner's Handbook with part number T3853295.

9950608 - NL Replace the Owner's Handbook with part number T3853296.

9950606 - SE Replace the Owner's Handbook with part number T3853297.

9950607 - JP Replace the Owner's Handbook with part number T3853298.

Repair time allowanceRepair code - 0.03 hrs



Genuine Parts Information

- Genuine parts. 1 x T3853290, Handbook English
- 1 x T3853292, Handbook German
- 1 x T3853293, Handbook French
- 1 x T3853294, Handbook Spanish
- 1 x T3853295, Handbook Italian
- 1 x T3853296, Handbook Dutch
- 1 x T3853297, Handbook Swedish
- 1 x T3853298, Handbook Japanese

Genuine Parts Ordering Instructions. **For Triumph Subsidiary and Overseas Distributor dealers using Triumph Warranty On-Line with Parts Auto Ordering Flag switched on:** Order all repair parts by submitting a New Prior through the Warranty On-Line system. Entering the above repair code in a New Prior will automatically add the parts required and labour times for this Service Bulletin.

For Overseas Distributor dealers NOT using Triumph Warranty On-Line or for Overseas Distributor dealers using Triumph Warranty On-Line with Parts Auto Ordering Flag switched off: Orders should be placed using the normal parts ordering procedure.

Genuine Parts Return Instructions Dealer to retain parts for 90 days. All parts must be stored in a secure, non-public accessed area and correctly identified with a completed warranty label. Thereafter the parts must be rendered unusable prior to scrapping.

TRIUMPH

Other Instructions

Before returning the motorcycle to the customer, download the latest tune to the engine control module using the current version of the Triumph Diagnostic Software.

Once completed, please mark the Service Record Book that the requirements of this bulletin have been complied with.

Replacement Procedure

Replace the Owner's Handbook and retain the old handbook as described in the Parts Return Instruction.

Warning

Throughout the following procedure, ensure that the motorcycle is stabilised and adequately supported to prevent the risk of injury from the motorcycle falling.

Note:

- **Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.**
- **The modified motorcycles can be identified by checking the 'VIN Enquiry' on Triumphonline.net.**

Warning

To prevent detachment of the seat during riding, after fitting always grasp the seat and pull firmly upwards. If the seat is not correctly secured, it will detach from the lock. A loose or detached seat could cause loss of motorcycle control and an accident.

1. Remove the rider's seat, as described in the Service Manual.
2. Remove the Owner's Handbook from the seat and check the handbook has not already been replaced.
3. If necessary replace the handbook with the part number listed above.
4. Install the handbook assembly into the rider's seat.
5. Refit the seat, as described in the Service Manual.

Circulation

(Initial and date when read and return to central file holder)

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2



Appendix A

EN.....	VIN 570059 to VIN 618677 motorcycles originally supplied with an English handbook assembly
DE.....	VIN 570059 to VIN 608868 motorcycles originally supplied with a German handbook assembly
FR.....	VIN 570059 to VIN 606952 motorcycles originally supplied with a French handbook assembly
ES.....	VIN 570059 to VIN 603200 motorcycles originally supplied with a Spanish handbook assembly
IT.....	VIN 570059 to VIN 608864 motorcycles originally supplied with an Italian handbook assembly
NL.....	VIN 570059 to VIN 607983 motorcycles originally supplied with a Dutch handbook assembly
SE.....	VIN 570059 to VIN 600680 motorcycles originally supplied with a Swedish handbook assembly
JP.....	VIN 570059 to VIN 618657 motorcycles originally supplied with a Japanese handbook assembly