

Technical Service Bulletin



PSS 46 Brake noise (non-hybrid vehicles) 3.0T with PR-1LE

46 14 81 2037044/1 April 23, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5	2013 - 2014	All	3.0T

Condition

- Customer may report that the front brakes squeal under the following conditions:
 - During the first stop in the morning when vehicle is back out of driveway.
 - When brakes are applied after driving direction is changed at slow speeds (such as during parking lot maneuvers).
- This condition may occur more frequently during cold weather conditions (without rain), and the noise will disappear as temperature increases.



Tip: This PSS TSB does not apply to Q5 2.0T and Hybrid models.

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues have been identified with the replaced parts.

Production Solution

Not applicable.

Technical Service Bulletin



Service

1. Explain to the customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application via the hyperlink in Accessaudi.com (Figure 1) or Technical Assistance page in Elsa (Figure 2).




Figure 1. Related Sites section on Accessaudi.com landing page



Figure 2. Technical Assistance page



Tip: For critical cases, create a TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.



Additional Information

All parts and service references provided in this TSB (2037044) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.