

Technical Service Bulletin



46 Squeal from front brakes (non-hybrid vehicles)_3.0T & 3.0TDI with PR-1LE

46 14 92 2037786/1 July 23, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5	2013 - 2014	Applies only to certain VINs; see Elsa	3.0T and 3.0 TDI

Condition

Customer may report hearing brake noise when the vehicle comes to a stop.

Technical Background

Not applicable.

Production Solution

Improved front brake pads.

Service

Replace the front brake pads according to the instructions in Elsa at: *Repair manual >> Chassis >> 46 Mechanical Components >> Removal and Installation >> Brake Pads, Front >> Brake Pads, 1LB/1LC/1LE/1LP.*

Technical Service Bulletin



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4617		
Damage Code:	0020		
Labor Operations:	2 wheels remove+reinstall	4405 2000	20 TU
	Brake pads, front remove+reinstall	4636 2050	50 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2037786/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
8R0698151L	1 set of brake pads for disc brakes	1
8R0615121A	Contact (wear sensor)	1

Additional Information

All parts and service references provided in this TSB (2037029) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.