

No.: 14 TS-21
August 12, 2014

TO: Service Locations

FROM: Service Systems Development

SUBJECT: **HDEP Camshaft Position Sensor Change**

ISSUE

Engine camshaft position sensor mounting bolts have been rotated to reduce cross threading. The new sensor is not backwards-compatible. This change took place on the DD13 beginning with engine serial number HDE0206808 while the DD15/16 change took place beginning with engine serial number HDE0208618. See figures below.

Both sensors are available for service.

Old Style Sensor (P/N: A0061535528)



New Style Sensor (P/N: A0071535928)



When a new camshaft housing is ordered, a new style sensor is included.

CONTACT INFORMATION

Please contact the Detroit[®] Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.