



# Technical Bulletin

---

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	2012-2014	All	All	All	All

## Condition

40 14 01 March 04, 2014 2033347 Supersedes V401301 dated March 20, 2013 to include additional model year applicability.

### CV Boot Replacement

CV boot damage identified.

## Technical Background

Recommended procedure for removing damaged CV boot.

## Production Solution

Not applicable.

# Technical Bulletin

---

## Service

If it is determined that a CV boot needs to be replaced, the boot should be removed and replaced without cutting or slicing the boot open. Once the CV Joint is removed the boot will slide off the axle shaft. Refer to repair manual group 40, removal procedure for drive axle disassembly, in ElsaWeb.

**⚠ Note:**

Claims will not be accepted if the CV Boot is cut or sliced.

All replaced attachment hardware must be returned with the replaced boot.



**CV Boots should not be cut or sliced upon removal.**



**CV Boots should slide off the driveshaft after the removal of the CV Joint.**



# Technical Bulletin

---

## Warranty

Information only.

## Required Parts and Tools

No Special Parts required.

No Special Tools required.

## Additional Information

**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**