

Technical Service Bulletin

46 3.0T & 3.0TDI Brake noise (PR-1LL)

46 14 96 2038647/1 October 20, 2014.

ſ	Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
	A8	2013 - 2014	All	3.0T & 3.0TDI	

Condition

Customer may report hearing brake squeal when the vehicle comes to a stop at slow speeds. In some cases, the noise may be intermittent and difficult to reproduce.

Technical Background

Not applicable.

Production Solution

Improved front brake pads and discs.

Service

- 1. Road test to verify concern.
- 2. Replace front brake pads, discs, and sensors (using the part numbers listed in this TSB) according to the instructions in Elsa at: *Repair manual >> Chassis >> 46 Mechanical Components >> Front Brakes >> Brake Rotor, Removing and Installing >> Brake Rotor, Removing and Installing Steel Brakes 1LL/1LJ and 1LN/1LX.*
- 3. Road test to verify that the noise is eliminated.

© 2014 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	4617				
Damage Code:	0020				
Labor Operations:	2 wheels removed + reinstalled	4405 2000	20 TU		
	2 front brake discs remove + reinstall	4650 2050	50 TU		
	2 brake pads, front remove + reinstall	4636 2050	70 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2038647/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4G0615301A	Front brake disc	2
4G0698151M	Front brake pads 1	
4H0615121J	Front brake wear indicators	2

Additional Information

All parts and service references provided in this TSB (2038647) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

^{© 2014} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.