

Technical Service Bulletin



20 MIL on, DTC P045600 stored in ECM - Repair Authorization

20 14 37 2038276/1 September 9, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2013 - 2014	See Elsa	Not Applicable
A5	2013 - 2014	See Elsa	Not Applicable
A5 cabriolet	2013 - 2014	See Elsa	Not Applicable
Q5	2013 - 2014	See Elsa	Not Applicable

Condition

- **DTC P045600** is stored in the engine control module (ECM), J623 (address word 01).
- Note that this repair authorization applies only to a specific list of VINs. If this repair authorization does not appear in ELSA when your VIN is entered, it does not apply.

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC code listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify the condition.
2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB (2038276) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.