# Audi

# Technical Service Bulletin

#### 70 Noises from the instrument panel area

70 14 42 2033711/2 December 18, 2014. Supersedes Technical Service Bulletin Group 70 number 13-30 dated April 25, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4	2013	A000001 - A209596 N00001 - N040070	All	
allroad	2013	A000001 - A209596	All	

#### Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised Warranty (Updated Damage Code)		
1	4/25/2013	Initial publication		

Squeak or rattle noises from the instrument panel area.

# **Technical Background**

Due to the multiple components that comprise the trim assembly, the panel surrounding the instrument cluster, MMI display screen, etc. can create these noises over bumps or when flexing.

### **Production Solution**

An improved instrument panel trim (Figure 1) is implemented in production.



Figure 1. Instrument panel trim.



# Technical Service Bulletin

## **Service**

Replace the instrument panel trim.

## **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	7018				
Damage Code:	0010				
Labor Operations:	Replace instrument panel trim	7018 9999	60 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2033711/2				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

# **Required Parts and Tools**

Part Number	Part Description	Quantity
8K1857186XX XXX	Trim	1
	(Use appropriate index and color code based on equipment variant)	

## **Additional Information**

All parts and service references provided in this TSB (2033711) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.