

[Next Unread Message](#)**View Message**

**Sent on** 06 05 2014 **Expires on** 06 19 2014  
**From** Parts and Service Division  
**Subject** Request for Parts: 2013-2014 RDX FCW Light On with/without DTC P0455/P0456

**To:** All Acura Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2013-2014 RDX Fuel Cap Warning Light On with/without DTC P0455 and/or P0456 Stored

**This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

**Background**

American Honda (AHM) is investigating certain 2013-2014 RDXs with a complaint of fuel cap warning light on with or without DTC P455 (EVAP System Large Leak Detected) and/or P456 (EVAP System Very Small Leak Detected) Stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to your attempting any further repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Both 2WD and AWD are accepted.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.