

[Next Unread Message](#)**View Message**

---

**Sent on** 03 31 2014 **Expires on** 04 14 2014  
**From** Parts and Service Division  
**Subject** Request for Parts: 2014 MDX MIL On with DTC P0158 and/or P0138 Stored

**To:** All Acura Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2014 MDX MIL On with DTC P0158 and/or P0138 Stored

This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2014 MDXs with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC P0158 (Front Secondary Heated Oxygen Sensor Circuit High Voltage) and/or P0138 (Rear Secondary Heated Oxygen Sensor Circuit High Voltage) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting any further repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. DTC P0158 and/or P0138 must be stored.
2. 2WD and AWD are accepted.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.