

[Next Unread Message](#)**View Message**

Sent on 03 17 2014 **Expires on** 03 27 2014
From Parts and Service Division
Subject Request for Parts: 2014 MDX MIL On with DTC P0158 and/or P0138 Stored

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2014 MDX MIL On with DTC P0158 and/or P0138 Stored

**This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda (AHM) is investigating certain 2014 MDXs with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC P0158 (Front Secondary Heated Oxygen Sensor Circuit High Voltage) and/or P0138 (Rear Secondary Heated Oxygen Sensor Circuit High Voltage) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting any further repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. DTC P0158 and/or P0138 must be stored.
2. 2WD and AWD are accepted.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.