



Countries:	AUSTRALIA, BRAZIL, CANADA, UNITED STATES, MEXICO, SOUTH AFRICA	Document ID:	IK0900019
Availability:	ISIS, Bus ISIS, FleetISIS	Revision:	3
Major System:	ENGINES	Created:	1/30/2009
Current Language:	English	Last Modified:	2/5/2014
Other Languages:	Portuguese ,	Author:	Jon Pierce
Viewed:	636		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 180	 186

Title: Cummins ISX belts issues with high fan center 5000i, 9000i models

Applies To: 5000 and 9000 models with Cummins ISX Engines

DESCRIPTION

Cummins ISX belts issues with high fan center 5000i, 9000i models

SYMPTOMS

- Belt fraying
- Belt breakage

TROUBLESHOOTING

1. Inspect belt pulleys for alignment, debris, paint or other foreign material
2. Inspect Tensioner

RESOLUTION

Repair issues observed during Troubleshooting

If inspection shows no problems and there have been multiple belt failures we recommend following attached Cummins Service/Parts Topics 09T8-8 and Instructions

OTHER RESOURCES

- [Cummins Service/Parts Topics 09T8-8](#)
- [Instructions](#)

Hide Details

Feedback Information

Viewed: 635

Helpful: 180

Not Helpful: 186

No Feedback Found

Copyright © 2014 Navistar, Inc.