



**Countries:** CANADA, UNITED STATES, PUERTO RICO  
**Document ID:** IK1200344  
**Availability:** ISIS, FleetISIS  
**Revision:** 2  
**Major System:** ENGINES  
**Created:** 12/15/2008  
**Current Language:** English  
**Last Modified:** 2/25/2014  
**Other Languages:** [Français](#), [Español](#),  
**Author:** Jay Weston  
**Viewed:** 1426

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark  <a href="#">View My Bookmarks</a>	Add to Favorites 	Print 	Provide Feedback 	Helpful  270	Not Helpful  155
---------------	------------------------	---	----------------------	-----------	----------------------	--------------------	------------------------

**Title: DTC 1373 on MaxxFORCE 11 and 13 During Actuator Test**

**Applies To: All MaxxFORCE 11 and 13 liter engines**

**DESCRIPTION**

Active DTC 1373 set during an Actuator Test

**POSSIBLE DIAGNOSTIC TROUBLE CODES**

DTC	MODULE	DESCRIPTION
1373	EIM	Cold Start Relay Fault

**RESOLUTION**

On MaxxFORCE 11 and 13 Liter engines, DTC 1373 will set during the Actuator test. This is due to a known fault in the calibration, and is being addressed in a future release. If you receive this code when performing an Actuator Test, cycle the key and clear the code (it will go inactive when the key is cycled).

Hide Details

Feedback Information

Viewed: 1425  
 Helpful: 270  
 Not Helpful: 155

No Feedback Found